INFORMATION REPORT INFORMATION REPORT

CENTRAL INTELLIGENCE AGENCY

This material contains information affecting the National Defense of the United States within the meaning of the Espionage Laws, Title 18, U.S.C. Secs. 793 and 794, the transmission or revelation of which in any manner to an unauthorized person is prohibited by law.

COUNTRY	Hungary	REPORT	
SUBJECT	Faulty Production of Disc Mines	DATE DISTR. 16 September 1955	
		NO. OF PAGES	
DATE OF INFO.		requirement no. RD	2
PLACE ACQUIRED		REFERENCES	
DATE ACQUIRED	This is	s UNEVALUATED Information	
	SOURCE EVALUATIONS ARE DEFINITIVE. APPRAIS	SAL OF CONTENT IS TENTATIVE.	25)

- 1. The Hungarian Ministry of War has ordered an investigation of the Borsodnadasdi Lemezgyar (the Steel Plate works of Borsodnadasd). The reason is the delivery of faulty steel plates and sheets to the Köbanyai Zomacarugyar, the former Lampert Works which were used by the latter in the manufacture of "tanyerakna" (i.e. plate or disc mines). The quantity involved is said to be 75% of the total supplied.
- 2. The Lampert works had to discard 70,000 kilos of their pressings because of faulty material. Director Miklos Csatari of Lampert, who was called back from a study tour in Czechoslovakia, explained the cause of the large proportion of rejects in the faulty steel supplied by the Borsodnadasdi Lemezgyar.
- 3. The supply department of the Ministry of War has been asked to make a list of all disc mines supplied to military establishments last year as they will have to be inspected.
- 4. Though the investigation was still in progress on 30 April, two engineers of the Borsodnadasdi Lemezgyar had been arrested and subject to courts-martial.

11 Lemezgyar had been arrested and subject to courts-martial.

25X1

STATE X ARMY X NAVY X AIR X FBI AEC (Note: Washington distribution indicated by "X"; Field distribution by "#".)

25X1